



Product Overview:

1. SATA Power Connector
2. External Interface:
 - 1x USB 3.1 (Type A Port)
 - 1x USB 3.1 (Type C Port)
3. PCIe x2 Connector

Installation:

1. Turn off your computer and unplug your power supply.
2. Open the case.
3. Insert the Host Controller Card into an available PCIe x4, x8 or x16 slot (PCIe Support: PCIe 2.0 x2, PCIe 3.0 x1) and secure the card with the screws.
4. Connect the SATA power connector to the power supply.
5. Close the case and restart your PC.

Driver Installation:

No driver installation is required for Windows 8 and above. The Host Controller Card is automatically recognized and is immediately ready for use.

Windows 7:

1. Insert the CD.
2. Run "setup.exe" and follow the instructions in the installation wizard until it is finished.
3. Restart the PC.
4. The USB 3.1 Host Controller Card is now ready for use.